



Final Assembly Packaging and Mechanical Items:

H2 WolfSpeed PCB SN Label

FD1  
FID1X2R  
FD2  
FID1X2R  
FD3  
FID1X2R  
FD4  
FID1X2R

Notes:

1. NP = do not populate.

2. R35 and R37 share the same footprint as C3 and C2. C3 and C2 are only populated when using the Miller clamp circuit.