



Final Assembly Packaging and Mechanical Items:

H2 Wolfspeed PCB SN Label

- Notes:
- 1. NP = do not populate.
 - 2. R36 and R37 share the same footprint as C3 and C2. C2 and C3 are only populated when using the Miller clamp circuit.

- FD1 FID1X2R
- FD2 FID1X2R
- FD3 FID1X2R
- FD4 FID1X2R